



Hennepin County Department of Housing, Community Works & Transit

701 Fourth Avenue South, Suite 400
Minneapolis, Minnesota 55415

612-348-9260, Phone
612-348-9710, Fax
www.hennepin.us

2/10/2012

GMHC - Greater Metropolitan Housing Corporation
15 S 5th St Suite 710
Minneapolis MN 55402
RE: 4330 Logan AVE N

Dear GMHC - Greater Metropolitan Housing Corporation:

The Hennepin County Housing, Community Works and Transit Department has completed a Lead-Based Paint Inspection and Risk Assessment (PIRA) at the above referenced address. Appendix D of the enclosed PIRA Report lists options for addressing each lead hazard identified during the PIRA. The options listed for each lead hazard range from abatement (removal or enclosure) to interim controls (paint stabilization). When choosing options for each lead hazard it is a good practice to consult with your construction manager and contractor to determine the best solutions for your property and your budget. Hennepin County Housing Community Works and Transit staff are also available for consultation on the contents of this report.

A clearance inspection should be conducted immediately following the lead hazard reduction work. Please notify our office two days in advance of the completion of the work so your property can be put on the clearance schedule.

The Federal Residential Lead-Based Paint Hazard Reduction Act, 42 U.S.C. 4852d, requires sellers and landlords of most residential housing built before 1978 to disclose all available records and reports concerning lead-based paint and/or lead-based paint hazards, including the test results contained in this notice, to purchasers and tenants at the time of sale or lease or upon lease renewal. This disclosure must occur even if hazard reduction or abatement has been completed. Failure to disclose these test results is a violation of the U.S. Department of Housing and Urban Development and the U.S. Environmental Protection Agency regulations at 24 CFR Part 35 and 40 CFR Part 745 and can result in a fine of up to \$11,000 per violation. To find out more information about your obligations under federal lead-based paint requirements call 1-800-424-LEAD.

Sincerely,

Ben Jones

Hennepin County
Housing, Community Works and Transit
(612) 366-9579



Lead-Based Paint Inspection and Risk Assessment Report

**4330 Logan AVE N
Minneapolis MN, 55412**

Prepared For:

**GMHC - Greater Metropolitan Housing Corporation
15 S 5th St Suite 710
Minneapolis, MN 55402**

By:

**Ben Jones
Hennepin County
Housing, Community Works and Transit
701 4th Ave S, Suite 400
Minneapolis, MN 55415-1843**

Minnesota License Number: LR2623

2/10/2012



**Hennepin County Housing,
Community Works and Transit**

Paint Inspection / Risk Assessment Summary

Site Address: 4330 Logan AVE N

Property Information:

Owner: GMHC - Greater Metropolitan Housing Corporation
15 S 5th St Suite 710
Minneapolis, MN 55402
(612) 399-0601

Date of Construction: 1941

Occupancy Status: Vacant

Inspection Date: 1/27/2012

Report Date: 9/10/2012

Summary of Findings: Lead-Based Paint and Lead Hazards were found.

Summary of Locations of Lead-Based Paint:

Exterior and Interior

Summary of Lead-Based Paint Hazards:

Dust Hazards: Window wells, window sills, and floors.

Soil Hazards: None detected at the time of inspection.

Paint Hazards: Cellar windows, several exterior walls, pieces interior and exterior trim, and doors.

Information Included in Report:

HUD Guidelines Part I (see cover page)

HUD Guidelines Part II

Appendix A: Dwelling Sketches

Appendix B: XRF Results

Appendix C: Analytical Results (If applicable)

HUD Guidelines Part III

Appendix D: Lead Hazard Reduction Options

Appendix E: Maintenance/Monitoring Schedule (If applicable)

Risk Assessor (for more information):

Ben Jones

Minnesota License Number: LR2623

Hennepin County

Housing, Community Works and Transit

701 4th Ave S, Suite 400

Minneapolis, MN 55415-1843

(612) 366-9579

Report prepared by:

Ben Jones

Hennepin County

Housing, Community Works and Tran

701 4th Ave S, Suite 400

Minneapolis, MN 55415-1843

(612) 366-9579



Hennepin County Housing Community Works and Transit

Appendix A: Dwelling Sketches

These sketches are diagrams of the exterior and interior rooms of the reference property. The room numbers on the sketches correspond to the "Room" column on the XRF report and the "Room #" column on the analytical sample sheets.


Each room in a dwelling unit or common area is given a room number including the Exterior and the Garage. Dwelling units and common areas are treated separately and individually numbered beginning with Room 02 (Room 01 is never used). The Exterior and Garage are numbered as part of the common areas.



Hennepin County Housing, Community Works & Transit Dwelling Sketch

Case Type	Tracking #	Property Address	Dwelling Unit	
GMHC/Fee For Service		4330 Logan Ave N, MPLS	SF	
Risk Assessor	Page Number	Exterior Floor Level	Drawn By	Date
Jones	Page 1 of 4	EXTERIOR	B.S.	1/27/11

02 HOUSE EXT
03 GARAGE
04
05
06
07
08
09
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32




Street used in address of residence: Logan Avenue N.



Hennepin County Housing, Community Works & Transit Dwelling Sketch

Case Type	Tracking #	Property Address	Dwelling Unit
GMHC/Fee For Service		4330 Logan Ave N, MPLS	SF
Risk Assessor	Page Number	Exterior / <u>Floor Level</u>	Drawn By Date
Jones	Page 2 of 4	BASEMENT	B.J. 1/27/11

- 02
- 03
- 04 BASEMENT
- 05 BSMT STR
- 06
- 07
- 08
- 09
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32



Street used in address of residence: **Logan Avenue N.**

This sketch is not to scale.




Hennepin County Housing, Community Works & Transit Dwelling Sketch

Case Type	Tracking #	Property Address	Dwelling Unit	
GMHC/Fee For Service		4330 Logan Ave N, MPLS	SF	
Risk Assessor	Page Number	Exterior / Floor Level	Drawn By	Date
Jones	Page 3 of 4	FLOOR 01	B.J.	1/27/12

- 02
- 03
- 04
- 05
- 06 Kitchen
- 07 NE BED RM
- 08 HALL
- 09 BATH
- 10 SE BED RM
- 11 LIVING RM
- 12 ENTRY
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32

C

V = Vinyl Window
CL = Closet




Street used in address of residence: Logan Avenue N.

This sketch is not to scale.



Hennepin County Housing, Community Works & Transit Dwelling Sketch

Case Type	Tracking #	Property Address	Dwelling Unit	
GMHC/Fee For Service		4330 Logan Ave N, MPLS	SF	
Risk Assessor	Page Number	Exterior / Floor Level	Drawn By	Date
Jones	Page 4 of 4	FLOOR 02	B.J.	1/27/12



Street used in address of residence: **Logan Avenue N.**

This sketch is not to scale.



**Appendix B:
XRF Results Report—Attached**

XRF risk assessment paint inspection conducted according to established HUD guidelines and according to the Hennepin County Housing, Community Works and Transit protocols.

Paint Standard

1.0 mg/cm²

Explanation of Column Headings:

- No - a machine generated sequence number
- XRF/Insp - the serial number of the machine and the initials of the inspector
- Site - specific unit of a multiple unit project (omitted for single family homes)
- Floor - Floor level
- Room - room being tested (see site diagrams also included)
- Wall - Wall side of the room starting with A on the street side and going clock-wise
- Component - what is being tested
- Substrate - the composition of the tested component
- Condition - condition of the paint
- Color - the color of the paint
- DI - Depth Index - the larger the number the deeper the lead-based paint layer
- Result - the result of the test
- Pbc - the total combined lead in the layers of paint
- Pbc Error - the error of the total combined lead level

Model and Serial numbers of Niton XRFs used:

Model #	Serial #
XLp300A	U9022
XLp300A	U9731
XLp303A	U17621
XLp305A	U25845

<u>Risk Assessors</u>	<u>Initials</u>	<u>License Number</u>
Brian Kløver	BK	369
Matt Moore	MM	614
Melisa Illies	MI	330
Michael Jensen	MJ	232
Jim Graham	JG	771
Ben Jones	BJ	2623
Isak Collins	IC	1278

No	XRF/Insp	Floor	ROOM	#	Wall	COMPONENT	SUBSTRATE	CONDITION	COLOR	DI	Results	PbC mg/cm ²	PbC Error mg/cm ²
785						Shutter Calibrate					411.56	8.1	0
786						Calibrate				1.07	Positive	1.1	0.1
787						Calibrate				1.04	Positive	1.1	0.1
788						Calibrate				1.09	Positive	1.1	0.1
789						Calibrate				1.34	Positive	4	1.7
790						Calibrate				1	Negative	< LOD	0.43
791	9022/I/C	1	Exterior	2	A	Wall	WOOD	FAIR	Beige	3.48	Positive	16.6	4.8
792	9022/I/C	1	Exterior	2	A	Window Casing	WOOD	FAIR	Beige	2.36	Positive	21.1	7.2
793	9022/I/C	1	Exterior	2	B	Wall	WOOD	FAIR	Beige	3.25	Positive	10.7	4.8
794	9022/I/C	1	Exterior	2	B	Door	WOOD	FAIR	WHITE	1.29	Positive	4.9	2
795	9022/I/C	1	Exterior	2	B	Door Threshold	WOOD	FAIR	WHITE	1.92	Positive	7.9	4.4
796	9022/I/C	1	Exterior	2	B	Door Jamb	WOOD	FAIR	WHITE	2.47	Positive	9.1	4.5
797	9022/I/C	1	Exterior	2	B	Door Casing	WOOD	FAIR	WHITE	3.06	Positive	< LOD	16.8
798	9022/I/C	1	Exterior	2	C	Wall	WOOD	FAIR	WHITE	4.89	Positive	20.5	6.8
799	9022/I/C	1	Exterior	2	D	Wall	WOOD	FAIR	WHITE	4.76	Positive	16.5	6.1
800	9022/I/C	1	Exterior	2	C	Celr Win Cas	WOOD	FAIR	WHITE	2.07	Positive	6.2	3.6
801	9022/I/C	1	Exterior	2	B	awning	METAL	FAIR	WHITE	1	Negative	< LOD	0.03
802	9022/I/C	1	Exterior	2	A	Door	WOOD	FAIR	WHITE	3.46	Positive	16.1	6
803	9022/I/C	1	Exterior	2	A	Str Rail Cap	METAL	FAIR	Black	1	Negative	0.22	0.14
804	9022/I/C	1	Exterior	2	B	Downspout	METAL	FAIR	WHITE	1	Negative	< LOD	0.03
805	9022/I/C	1	Garage	3	A	Wall	WOOD	FAIR	Blue	2.52	Positive	11.3	4.9
806	9022/I/C	1	Garage	3	B	Wall	WOOD	FAIR	Blue	2.56	Positive	13.8	5.5
807	9022/I/C	1	Garage	3	C	Wall	WOOD	FAIR	Blue	2.53	Positive	12.1	5.1
808	9022/I/C	1	Garage	3	D	Wall	WOOD	FAIR	Blue	3.02	Positive	16.1	5.8
809	9022/I/C	1	Garage	3	D	Overhead Dr Cas	WOOD	FAIR	Blue	2.62	Positive	10	4.8
810	9022/I/C	1	Garage	3	D	Overhead Dr	METAL	FAIR	WHITE	1	Negative	< LOD	0.03
811	9022/I/C	1	Garage	3	A	Door	METAL	FAIR	WHITE	1	Negative	< LOD	0.05
812	9022/I/C	1	Garage	3	A	Door Casing	WOOD	FAIR	Blue	1	Negative	< LOD	0.03
813	9022/I/C	1	Garage	3	A	Window Casing	WOOD	FAIR	WHITE	2.69	Positive	14.2	5.5
814	9022/I/C	1	Garage	3	A	Window Sash	WOOD	FAIR	WHITE	2.98	Positive	12.9	5.1
815	9022/I/C	Bsmt	Basement	4	A	Wall	CONCRETE	FAIR	WHITE	1	Negative	< LOD	0.03
816	9022/I/C	Bsmt	Basement	4	B	Wall	CONCRETE	FAIR	WHITE	1.85	Negative	< LOD	0.04
817	9022/I/C	Bsmt	Basement	4	C	Wall	CONCRETE	FAIR	WHITE	2.5	Negative	< LOD	0.05
818	9022/I/C	Bsmt	Basement	4	D	Wall	CONCRETE	FAIR	WHITE	7.76	Negative	< LOD	0.37
819	9022/I/C	Bsmt	Basement	4	D	Floor	VINYL	FAIR	Beige	1	Negative	< LOD	0.03
820	9022/I/C	Bsmt	Basement	4	A	Door Casing	WOOD	FAIR	WHITE	1.66	Null	< LOD	1.65
821	9022/I/C	Bsmt	Basement	4	A	Door Casing	WOOD	FAIR	WHITE	2.01	Positive	1.6	0.5
822	9022/I/C	Bsmt	Basement	4	A	Door	WOOD	FAIR	WHITE	1.95	Positive	1.8	0.5
823	9022/I/C	Bsmt	Basement	4	B	Celr Win Sash	WOOD	FAIR	WHITE	1.79	Positive	3.1	0.8

No	XRF/Insp	Floor ROOM	#	Wall	COMPONENT	SUBSTRATE	CONDITION	COLOR	DI	Results	PbC mg/cm ²	PbC Error mg/cm ²
824	9022/IC	Bsmt Basement	4	B	CeIr Win Cas	WOOD	FAIR	WHITE	1.78	Positive	2.7	1.4
825	9022/IC	Bsmt Basement	4	D	CeIr Support	WOOD	FAIR	WHITE	2.71	Negative	< LOD	0.29
826	9022/IC	Bsmt Basement	4	D	CeIr Beam	WOOD	FAIR	WHITE	1.17	Negative	< LOD	0.07
827	9022/IC	Bsmt Basement	4	C	Chimney	BRICK	FAIR	Beige	2.27	Negative	< LOD	0.04
828	9022/IC	Bsmt Bsmt Stair	5	A	Wall	PLASTER	FAIR	Beige	8.43	Negative	< LOD	1.38
829	9022/IC	Bsmt Bsmt Stair	5	B	Wall	PLASTER	FAIR	Beige	8.21	Negative	< LOD	1.26
830	9022/IC	Bsmt Bsmt Stair	5	C	Wall	PLASTER	FAIR	Beige	2.63	Negative	< LOD	1.25
831	9022/IC	Bsmt Bsmt Stair	5	D	Ceiling	PLASTER	FAIR	Beige	2.8	Negative	< LOD	2.2
832	9022/IC	Bsmt Bsmt Stair	5	D	Wall	VINYL	INTACT	Beige	1	Null	< LOD	0.03
833	9022/IC	Bsmt Bsmt Stair	5	D	Wall	VINYL	INTACT	Beige	3.7	Negative	< LOD	0.03
834	9022/IC	Bsmt Bsmt Stair	5	D	Str Tread	VINYL	INTACT	Beige	1.97	Negative	< LOD	0.03
835	9022/IC	Bsmt Bsmt Stair	5	D	Str Risers	VINYL	INTACT	Beige	1	Negative	< LOD	0.03
836	9022/IC	Bsmt Bsmt Stair	5	D	Str Baseboard	WOOD	FAIR	WHITE	1	Negative	< LOD	0.08
837	9022/IC	Bsmt Bsmt Stair	5	A	Str Rail Cap	WOOD	FAIR	NATRL	1	Negative	< LOD	0.05
838	9022/IC	Bsmt Bsmt Stair	5	A	Door Casing	WOOD	FAIR	NATRL	1.2	Negative	< LOD	0.07
839	9022/IC	Bsmt Bsmt Stair	5	A	Door	WOOD	FAIR	NATRL	1.69	Negative	< LOD	0.24
840	9022/IC	Bsmt Bsmt Stair	5	A	Baseboard	WOOD	FAIR	NATRL	1	Negative	< LOD	0.08
841	9022/IC	Bsmt Bsmt Stair	5	A	Wall	PLASTER	FAIR	Beige	1.44	Negative	< LOD	0.08
842	9022/IC	Bsmt Bsmt Stair	5	A	Wall lwr	PLASTER	FAIR	Pink	10	Negative	< LOD	1.38
843	9022/IC	Bsmt Bsmt Stair	5	B	Wall lwr	PLASTER	FAIR	Pink	3.18	Negative	< LOD	0.29
844	9022/IC	Bsmt Bsmt Stair	5	D	Wall lwr	PLASTER	FAIR	Pink	5.21	Negative	< LOD	0.25
845	9022/IC	Bsmt Bsmt Stair	5	B	Wall	PLASTER	FAIR	Beige	2.66	Negative	< LOD	0.05
846	9022/IC	Bsmt Bsmt Stair	5	C	Wall	PLASTER	FAIR	Pink	8.7	Negative	< LOD	1.41
847	9022/IC	Bsmt Bsmt Stair	5	D	Wall	PLASTER	FAIR	Yellow	5.44	Null	< LOD	0.24
848	9022/IC	Bsmt Bsmt Stair	5	D	Wall	PLASTER	FAIR	Yellow	4.8	Negative	< LOD	0.75
849	9022/IC	Bsmt Bsmt Stair	5	D	Floor	VINYL	FAIR	Beige	6.26	Negative	< LOD	1.31
850	9022/IC	Bsmt Bsmt Stair	5	D	Floor	VINYL	FAIR	Beige	1	Negative	< LOD	0.03
851	9022/IC	Bsmt Bsmt Stair	5	C	Door Casing	WOOD	FAIR	NATRL	1	Negative	< LOD	0.07
852	9022/IC	Bsmt Bsmt Stair	5	C	Door	WOOD	FAIR	NATRL	1	Negative	< LOD	0.14
853	9022/IC	Bsmt Bsmt Stair	5	B	Window Casing	WOOD	FAIR	NATRL	3.69	Negative	< LOD	0.4
854	9022/IC	Bsmt Bsmt Stair	5	B	Cab Outside	WOOD	FAIR	NATRL	1.14	Negative	< LOD	0.02
855	9022/IC	Bsmt Bsmt Stair	5	B	Cab Shelf	WOOD	FAIR	NATRL	1	Negative	< LOD	0.11
856	9022/IC	Bsmt Bsmt Stair	5	D	Baseboard	WOOD	FAIR	NATRL	1	Negative	< LOD	0.06
857	9022/IC	Bsmt Bsmt Stair	5	D	Shelf	WOOD	FAIR	NATRL	1	Negative	< LOD	0.07
858	9022/IC	Bsmt Bsmt Stair	5	A	Mini Blinds	VINYL	FAIR	Beige	1	Negative	< LOD	0.03
859	9022/IC	Bsmt Bsmt Stair	5	A	Wall	PLASTER	FAIR	Brown	1.16	Negative	< LOD	0.03
860	9022/IC	Bsmt Bsmt Stair	5	B	Wall	PLASTER	FAIR	Brown	1.75	Negative	< LOD	0.03
861	9022/IC	Bsmt Bsmt Stair	5	C	Wall	PLASTER	FAIR	Brown	1	Negative	< LOD	0.03
862	9022/IC	Bsmt Bsmt Stair	5	D	Wall	PLASTER	FAIR	Brown	3.47	Null	< LOD	0.11

No	XRF/Insp	Floor	ROOM	#	Wall	COMPONENT	SUBSTRATE	CONDITION	COLOR	DI	Results	PbC mg/cm ²	PbC Error mg/cm ²
863	9022/IC	1	NE Bedroom	7	D	Wall	PLASTER	FAIR	Brown	6.56	Negative	< LOD	0.15
864	9022/IC	1	NE Bedroom	7	D	Ceiling	PLASTER	INTACT	WHITE	1.88	Negative	< LOD	0.05
865	9022/IC	1	NE Bedroom	7	D	Floor	WOOD	FAIR	NATRL	1	Negative	< LOD	0.06
866	9022/IC	1	NE Bedroom	7	D	Baseboard	WOOD	FAIR	WHITE	2.84	Negative	< LOD	0.68
867	9022/IC	1	NE Bedroom	7	B	Window Sill	WOOD	FAIR	WHITE	1	Negative	< LOD	0.04
868	9022/IC	1	NE Bedroom	7	D	Door Casing	WOOD	FAIR	WHITE	3.63	Negative	< LOD	0.45
869	9022/IC	1	NE Bedroom	7	D	Door	WOOD	FAIR	WHITE	3.04	Negative	< LOD	0.59
870	9022/IC	1	NE Bedroom	7	C	Mini Blinds	VINYL	FAIR	Beige	1	Negative	< LOD	0.03
871	9022/IC	1	NE Bedroom	7	D	Cist Wall	PLASTER	FAIR	WHITE	2.52	Negative	< LOD	1.29
872	9022/IC	1	NE Bedroom	7	D	Cist Bracket	WOOD	FAIR	WHITE	2.05	Negative	< LOD	0.46
873	9022/IC	1	NE Bedroom	7	D	Cist Shelf	WOOD	FAIR	WHITE	3.57	Negative	< LOD	0.2
874	9022/IC	1	NE Bedroom	7	D	Cist hatch	WOOD	FAIR	WHITE	1.72	Negative	< LOD	0.23
875	9022/IC	1	Hall	8	A	Wall	PLASTER	FAIR	Brown	3.79	Null	0.6	0.2
876	9022/IC	1	Hall	8	A	Wall	PLASTER	FAIR	Brown	3.68	Negative	0.6	0.1
877	9022/IC	1	Hall	8	B	Wall	PLASTER	FAIR	Brown	4.4	Negative	0.8	0.1
878	9022/IC	1	Hall	8	C	Wall	PLASTER	FAIR	Brown	4.21	Negative	0.5	0.2
879	9022/IC	1	Hall	8	D	Wall	PLASTER	FAIR	Brown	4.68	Negative	< LOD	0.75
880	9022/IC	1	Hall	8	D	Ceiling	PLASTER	INTACT	WHITE	5.26	Negative	< LOD	0.6
881	9022/IC	1	Hall	8	D	Floor	WOOD	FAIR	NATRL	1.26	Negative	< LOD	0.11
882	9022/IC	1	Hall	8	D	Baseboard	WOOD	FAIR	WHITE	5.31	Negative	0.4	0.2
883	9022/IC	1	Hall	8	B	Door Casing	WOOD	FAIR	WHITE	3.09	Negative	< LOD	0.36
884	9022/IC	1	Hall	8	B	Door	WOOD	FAIR	WHITE	2.25	Negative	0.17	0.09
885	9022/IC	1	Hall	8	C	Hatch	WOOD	FAIR	WHITE	2.79	Negative	< LOD	0.38
886	9022/IC	1	Hall	8	C	Cist Wall	PLASTER	FAIR	Beige	1.18	Negative	< LOD	0.04
887	9022/IC	1	Hall	8	C	Cist Bracket	WOOD	FAIR	Beige	1.69	Negative	< LOD	0.25
888	9022/IC	1	Bath	9	A	Wall	PLASTER	FAIR	Blue	1	Negative	< LOD	0.03
889	9022/IC	1	Bath	9	B	Wall	PLASTER	FAIR	Blue	1	Negative	< LOD	0.03
890	9022/IC	1	Bath	9	C	Wall	PLASTER	FAIR	Blue	1.28	Negative	< LOD	0.03
891	9022/IC	1	Bath	9	D	Wall	PLASTER	FAIR	Blue	10	Negative	< LOD	1.56
892	9022/IC	1	Bath	9	D	Ceiling	PLASTER	FAIR	WHITE	10	Negative	< LOD	1.01
893	9022/IC	1	Bath	9	A	Floor	CERAMIC	INTACT	Beige	1.32	Negative	0.2	0.12
894	9022/IC	1	Bath	9	A	Door Casing	WOOD	FAIR	WHITE	2.42	Negative	< LOD	0.29
895	9022/IC	1	Bath	9	A	Door	WOOD	FAIR	WHITE	2.34	Negative	< LOD	0.27
896	9022/IC	1	Bath	9	D	Baseboard	WOOD	FAIR	WHITE	1	Negative	< LOD	0.03
897	9022/IC	1	Bath	9	D	Wains Coating	WOOD	FAIR	WHITE	1.28	Null	< LOD	0.11
898	9022/IC	1	Bath	9	D	Wains Coating	WOOD	FAIR	WHITE	5.84	Negative	< LOD	0.2
899	9022/IC	1	Bath	9	D	Cab Outside	WOOD	FAIR	WHITE	1.78	Negative	< LOD	0.06
900	9022/IC	1	Bath	9	C	Window Sill	WOOD	FAIR	WHITE	10	Negative	< LOD	0.95
901	9022/IC	1	Bath	9	C	Mini Blinds	VINYL	FAIR	WHITE	10	Null	< LOD	0.25

No	XRF/Insp	Floor	ROOM	#	Wall	COMPONENT	SUBSTRATE	CONDITION	COLOR	DI	Results	PbC mg/cm ²	PbC Error mg/cm ²
902	9022/IC	1	Bath	9	C	Mini Blinds	VINYL	FAIR	WHITE	1	Negative	< LOD	0.03
903	9022/IC	1	Bath	9	B	Wall	VINYL	INTACT	Blue	1	Negative	< LOD	0.03
904	9022/IC	1	Bath	9	B	Tub	VINYL	INTACT	Blue	1	Negative	< LOD	0.03
905	9022/IC	1	SE Bedroom	10	A	Wall	PLASTER	FAIR	Blue	2.75	Negative	0.14	0.07
906	9022/IC	1	SE Bedroom	10	B	Wall	PLASTER	FAIR	Blue	4.21	Null	< LOD	0.34
907	9022/IC	1	SE Bedroom	10	B	Wall	PLASTER	FAIR	Blue	2.7	Negative	0.15	0.08
908	9022/IC	1	SE Bedroom	10	C	Wall	PLASTER	FAIR	Blue	3.11	Negative	< LOD	0.27
909	9022/IC	1	SE Bedroom	10	D	Wall	PLASTER	FAIR	Blue	1.92	Negative	< LOD	0.17
910	9022/IC	1	SE Bedroom	10	D	Floor	PLASTER	INTACT	White	2.78	Negative	< LOD	1.23
911	9022/IC	1	SE Bedroom	10	D	Floor	WOOD	FAIR	NATRL	1.56	Negative	< LOD	0.09
912	9022/IC	1	SE Bedroom	10	D	Baseboard	WOOD	FAIR	WHITE	2.51	Negative	< LOD	0.4
913	9022/IC	1	SE Bedroom	10	D	Window Sill	WOOD	FAIR	WHITE	1.43	Positive	2.4	1.1
914	9022/IC	1	SE Bedroom	10	D	Window Casing	WOOD	FAIR	WHITE	2.56	Negative	< LOD	0.35
915	9022/IC	1	SE Bedroom	10	D	Window Sill	WOOD	FAIR	WHITE	2.33	Positive	2.9	1
916	9022/IC	1	SE Bedroom	10	D	Mini Blinds	VINYL	FAIR	WHITE	1	Negative	< LOD	0.03
917	9022/IC	1	SE Bedroom	10	B	Cist Wall	PLASTER	FAIR	Beige	2.13	Negative	< LOD	2.63
918	9022/IC	1	SE Bedroom	10	B	Cist Bracket	WOOD	FAIR	Beige	1.71	Negative	< LOD	0.4
919	9022/IC	1	SE Bedroom	10	B	Cist Shelf	WOOD	FAIR	Beige	1	Negative	< LOD	0.03
920	9022/IC	1	SE Bedroom	10	B	Door Casing	WOOD	FAIR	WHITE	1.7	Negative	< LOD	0.23
921	9022/IC	1	SE Bedroom	10	B	Door	WOOD	FAIR	WHITE	1.03	Negative	< LOD	0.13
922	9022/IC	1	Living Room	11	A	Wall	PLASTER	FAIR	Brown	10	Negative	< LOD	1.41
923	9022/IC	1	Living Room	11	B	Wall	PLASTER	FAIR	Brown	10	Negative	< LOD	1.45
924	9022/IC	1	Living Room	11	C	Wall	PLASTER	FAIR	Brown	10	Negative	< LOD	1.41
925	9022/IC	1	Living Room	11	D	Wall	PLASTER	FAIR	Brown	10	Null	< LOD	0.37
926	9022/IC	1	Living Room	11	D	Wall	PLASTER	FAIR	Brown	10	Negative	< LOD	1.04
927	9022/IC	1	Living Room	11	D	Ceiling	PLASTER	INTACT	WHITE	1.97	Negative	< LOD	0.03
928	9022/IC	1	Living Room	11	D	Floor	WOOD	FAIR	NATRL	3.02	Negative	< LOD	0.23
929	9022/IC	1	Living Room	11	D	Baseboard	WOOD	FAIR	WHITE	4.88	Negative	< LOD	0.6
930	9022/IC	1	Living Room	11	D	Window Sill	WOOD	FAIR	WHITE	5.34	Negative	0.7	0.3
931	9022/IC	1	Living Room	11	D	Window Sill	WOOD	FAIR	WHITE	2.67	Negative	0.6	0.1
932	9022/IC	1	Living Room	11	D	Window Casing	WOOD	FAIR	WHITE	3.51	Negative	< LOD	0.35
933	9022/IC	1	Living Room	11	D	Mini Blinds	VINYL	FAIR	WHITE	1	Negative	< LOD	0.03
934	9022/IC	1	Living Room	11	B	Door Casing	WOOD	FAIR	WHITE	2.54	Negative	< LOD	0.24
935	9022/IC	1	Living Room	11	B	Door	WOOD	FAIR	WHITE	6.29	Negative	< LOD	0.47
936	9022/IC	1	Living Room	11	D	Mini Blinds	VINYL	FAIR	WHITE	1.47	Negative	< LOD	0.03
937	9022/IC	1	Kitchen	6	A	Floor	VINYL	FAIR	Beige	1	Negative	< LOD	0.03
938						Calibrate				1	Null	1	0.5
939						Calibrate				1	Positive	1	0.1
940						Calibrate				1.01	Positive	1	0.1

No	XRF/Insp	Floor	ROOM	#	Wall	COMPONENT	SUBSTRATE	CONDITION	COLOR	DI	Results	PbC mg/cm ²	PbC Error mg/cm ²
941						Calibrate				1.04	Positive	1.1	0.1

NOTES: The soffit, fascia, and upper walls on the exterior of the dwelling are too high to test. These exterior building components are painted wood that is in fair or poor condition, and need to be included in the lead reduction work. All first and second floor windows are vinyl inserts that do not contain lead.

No	XRF/Insp	Floor	ROOM	#	Wall	COMPONENT	SUBSTRATE	CONDITION	COLOR	DI	Results	PbC mg/cm ²	PbC Error mg/cm ²
1289						Shutter Calibrate					372.66	3.36	0
1290						Calibrate				1.12	Positive	1	0.1
1291						Calibrate				1.13	Positive	1.1	0.1
1292						Calibrate				1.14	Positive	1.1	0.1
1293						Calibrate				1.36	Positive	3.8	1.7
1294						Calibrate				1	Negative	0.28	0.15
1295	25845/BJ	SECOND	UPPER BR	13	A	Cist Wall	DRYWALL	FAIR	WHITE	1	Negative	< LOD	0.03
1296	25845/BJ	SECOND	UPPER BR	13	A	Cist Shelf	WOOD	INTACT	Grey	1	Negative	< LOD	0.03
1297	25845/BJ	SECOND	UPPER BR	13	A	Cist Bracket	WOOD	FAIR	WHITE	1	Negative	< LOD	0.03
1298	25845/BJ	SECOND	UPPER BR	13	A	Cist Floor	WOOD	FAIR	NATRL	1.52	Negative	< LOD	0.04
1299	25845/BJ	SECOND	UPPER BR	13	A	Cist Baseboard	WOOD	INTACT	Grey	1	Negative	< LOD	0.03
1300	25845/BJ	SECOND	UPPER BR	13	A	Cist Hatch	WOOD	FAIR	Grey	1	Negative	< LOD	0.03
1301	25845/BJ	SECOND	UPPER BR	13	A	Cist Hatch Cas	WOOD	FAIR	Grey	1.1	Negative	< LOD	0.04
1302	25845/BJ	SECOND	UPPER BR	13	A	Cist Door Jmb	WOOD	FAIR	Grey	1	Negative	< LOD	0.03
1303	25845/BJ	SECOND	UPPER BR	13	A	Cist Door	WOOD	FAIR	Grey	4.77	Negative	< LOD	0.25
1304	25845/BJ	SECOND	UPPER BR	13	A	Cist Door Thrsh	WOOD	FAIR	Grey	1	Negative	< LOD	0.03
1305	25845/BJ	SECOND	UPPER BR	13	A	Cist Ceiling	DRYWALL	FAIR	WHITE	1	Negative	< LOD	0.03
1306	25845/BJ	SECOND	UPPER BR	13	A	Wall	DRYWALL	FAIR	Grey	1.2	Negative	< LOD	0.03
1307	25845/BJ	SECOND	UPPER BR	13	B	Wall	DRYWALL	FAIR	Grey	1	Negative	< LOD	0.03
1308	25845/BJ	SECOND	UPPER BR	13	C	Cist Wall	DRYWALL	FAIR	Beige	1	Null	< LOD	0.03
1309	25845/BJ	SECOND	UPPER BR	13	D	Wall	DRYWALL	FAIR	Grey	1.87	Negative	< LOD	0.05
1310	25845/BJ	SECOND	UPPER BR	13	D	Ceiling	DRYWALL	INTACT	WHITE	1	Negative	< LOD	0.03
1311	25845/BJ	SECOND	UPPER BR	13	D	Floor	WOOD	FAIR	NATRL	1	Negative	< LOD	0.03
1312	25845/BJ	SECOND	UPPER BR	13	D	Baseboard	WOOD	FAIR	Grey	1	Negative	< LOD	0.04
1313	25845/BJ	SECOND	UPPER BR	13	D	Window Sill	WOOD	FAIR	Grey	2.02	Positive	3.8	1.8
1314	25845/BJ	SECOND	UPPER BR	13	D	Window Casing	WOOD	FAIR	Grey	2.15	Negative	< LOD	0.11
1315	25845/BJ	SECOND	UPPER BR	13	D	Window Sash	VINYL	INTACT	WHITE	1	Negative	< LOD	0.03
1316	25845/BJ	SECOND	UPPER BR	13	D	Mini Blinds	VINYL	FAIR	WHITE	1	Null	< LOD	0.03
1317	25845/BJ	SECOND	UPPER BR	13	C	Drawer	WOOD	FAIR	Grey	1.15	Negative	< LOD	0.05
1318	25845/BJ	SECOND	UPPER BR	13	A	Countertop	LAMINATE	INTACT	Blue	1	Negative	< LOD	0.03
1319	25845/BJ	SECOND	UPPER BR	13	A	Railing	VINYL	INTACT	Blue	2.52	Negative	< LOD	0.1
1320	25845/BJ	FIRST	UPPER BR	13	A	Str Rail Cap	WOOD	FAIR	NATRL	1	Negative	< LOD	0.03
1321	25845/BJ	FIRST	UPPER BR	13	A	Str Tread	WOOD	FAIR	Grey	1	Negative	< LOD	0.04
1322	25845/BJ	FIRST	UPPER BR	13	A	Str Risers	WOOD	FAIR	Grey	1	Negative	< LOD	0.04
1323	25845/BJ	FIRST	UPPER BR	13	A	Str Baseboard	WOOD	FAIR	Grey	1	Negative	< LOD	0.04
1324	25845/BJ	FIRST	UPPER BR	13	A	Str Wall	DRYWALL	FAIR	Grey	1	Negative	< LOD	0.03
1325	25845/BJ	FIRST	UPPER BR	13	A	Door Casing	WOOD	FAIR	Grey	1	Negative	< LOD	0.03
1326	25845/BJ	FIRST	UPPER BR	13	A	Door Jamb	WOOD	FAIR	Grey	1	Negative	< LOD	0.03
1327	25845/BJ	FIRST	UPPER BR	13	A	Door	WOOD	FAIR	Grey	4.56	Negative	< LOD	0.52

No	XRF/Insp	Floor	ROOM	#	Wall COMPONENT	SUBSTRATE	CONDITION	COLOR	DI	Results	PbC mg/cm ²	PbC Error mg/cm ²
1328	25845/BJ	FIRST	Front Entry	12	A Wall	PLASTER	INTACT	Yellow	3.12	Negative	< LOD	1.46
1329	25845/BJ	FIRST	Front Entry	12	B Wall	PLASTER	INTACT	Yellow	4.61	Negative	< LOD	1.11
1330	25845/BJ	FIRST	Front Entry	12	C Wall	PLASTER	INTACT	Yellow	2.48	Null	< LOD	1.03
1331	25845/BJ	FIRST	Front Entry	12	C Wall	PLASTER	INTACT	Yellow	4.95	Null	0.5	0.2
1332	25845/BJ	FIRST	Front Entry	12	C Wall	PLASTER	INTACT	Yellow	3.68	Negative	< LOD	1.16
1333	25845/BJ	FIRST	Front Entry	12	D Cist Wall	PLASTER	FAIR	WHITE	3.8	Negative	< LOD	3.07
1334	25845/BJ	FIRST	Front Entry	12	D Ceiling	PLASTER	INTACT	WHITE	10	Negative	< LOD	1.25
1335	25845/BJ	FIRST	Front Entry	12	C Floor	CERAMIC	INTACT	Beige	1.43	Negative	< LOD	0.04
1336	25845/BJ	FIRST	Front Entry	12	C Baseboard	WOOD	FAIR	WHITE	3.83	Negative	< LOD	0.38
1337	25845/BJ	FIRST	Front Entry	12	A Door Casing	WOOD	FAIR	WHITE	4.54	Negative	< LOD	0.6
1338	25845/BJ	FIRST	Front Entry	12	A Door	WOOD	FAIR	WHITE	6.33	Negative	< LOD	0.59
1339	25845/BJ	FIRST	Front Entry	12	D Cist Shelf	WOOD	FAIR	WHITE	1.6	Negative	< LOD	0.15
1340	25845/BJ	FIRST	Front Entry	12	D Cist Door	WOOD	FAIR	WHITE	3.37	Negative	< LOD	0.38
1341	25845/BJ	FIRST	Front Entry	12	D Cist Mail Box	WOOD	FAIR	WHITE	1.76	Negative	< LOD	0.06
1342												
1343												
1344												

NOTES: All first and second floor windows are vinyl inserts that do not contain lead.



Hennepin County Housing Community Works and Transit

**Appendix C:
Analytical Results---Attached**

**Analytical Laboratories:
Legend Technical Services, Inc.**

AIHA #101095
88 Empire Drive
St. Paul, MN 55103
651-642-1150

Schneider Laboratories, Inc.

AIHA #100527
2512 West Cary Street
Richmond, VA 23220-5117
804-353-6778

EMSL Analytical, Inc

Primary Facility
AHIA #163162
14375 23rd Ave N
Minneapolis, MN 55447
763-449-4922

EMSL Analytical, Inc

Back-up Facility
AIHA #100194
3 Cooper St
Westmont, MJ 08108
800-220-3675

Dust wipes and soil samples collected by Minnesota licensed risk assessors and according to HUD guidelines in accordance with the Hennepin County Housing, Community Works and Transit protocols.

A copy of the analytical results is attached. The US Environmental Protection Agency Dust Wipe standards are listed below. If a dust wipe exceeds these standards, the lead dust is considered a lead hazard. The Minnesota Soil Hazard level is listed below. If a soil sample exceeds the standard, the soil is considered a lead hazard.

Floor Wipe (FW)	40 μ /ft ²
Window Sill (WS)	250 μ /ft ²
Window Well (WW)	400 μ /ft ²
Soil	100 ppm

SCHNEIDER LABORATORIES GLOBAL

INCORPORATED

2512 W. Cary Street • Richmond, Virginia • 23220-5117
804-353-6778 • 800-785-LABS (5227) • (FAX) 804-359-1475

Over 25 Years of Excellence in Service and Technology

AIHA/ELLAP 100527, ISO/IEC 17025, NVLAP 101150-0, VELAP 460135, NYELAP/NELAC 11413

LABORATORY ANALYSIS REPORT

Lead Analysis based on EPA 7000B Method

Using SLI P27 A14

ACCOUNT #: 4040-12-1565

CLIENT: Hennepin CO Dept Housing Community

ADDRESS: 701 4th Avenue South
Minneapolis, MN 55415

DATE RECEIVED: 1/30/2012

DATE ANALYZED: 1/30/2012

DATE REPORTED: 1/31/2012

PROJECT NAME:

JOB LOCATION: 4330 Logan Ave N

PROJECT NO.:

PO NO.: HNCTY-50762

Sample Type: WIPE

SLI Sample No.	Client Sample No.	Collection Date	Sample Description	Sample Area (ft ²)	Total Lead (µg)*	Lead Conc (µg/ft ²)
31335297	01	1/27/2012	10:30 AM FW Bsmt V	1.00	102.2	102.2
31335298	02	1/27/2012	10:30 AM FW Entry Crm	1.00	150.4	150.4
31335299	03	1/27/2012	10:30 AM WW LR V	0.25	270.1	1,080.3
31335300	04	1/27/2012	10:30 AM FW SE BR W	1.00	< 10.0	< 10.0
31335301	05	1/27/2012	10:30 AM WS SE BR W	0.22	107.5	488.9
31335302	06	1/27/2012	10:30 AM FW Bath CRM	1.00	< 10.0	< 10.0
31335303	07	1/27/2012	10:30 AM FW Upper BR W	1.00	< 10.0	< 10.0
31335304	08	1/27/2012	10:30 AM WS Upper BR W	0.25	20.0	80.1
31335305	09	1/27/2012	10:30 AM WW Upper BR V	0.27	772.3	2,860.5
31335306	10	1/27/2012	10:30 AM Field Blank		< 10.0	

Analysis Run ID: 49394

Analyst: MOHAMMED ELTILIB

Total Number of Pages in Report: 1

Results relate only to samples as received by the laboratory.



Reviewed By

Tammie Olagbaju, QA Analyst

Visit www.slabinc.com for current certifications.

Final concentration calculations are based on client supplied information.

*Minimum Reporting Limit: 10.0 µg. EPA Lead Hazard Std: 40 µg/ft² floors and 250 µg/ft² interior window sills, based on weighted avg of all samples taken. EPA Clearance Std: 40 µg/ft² floors, 250 µg/ft² interior window sills, 400 µg/ft² window troughs. MDLs and resulting reporting limits are based on ASTM E 1792 compliant media. *Data precision justifies 2 sig figures. All internal QC parameters were met. Unusual sample conditions, if any, are described.*



SCHNEIDER LABORATORIES GLOBAL, INC.
 2512 West Cary Street, Richmond, Virginia 23220-5117
 804-353-6778 • 800-785-LABS (5227) • Fax 804-359-1475
 www.slabinc.com e-mail: info@slabinc.com

WO1 WorkOrderKey

 V : \ 865 \ 865087

Submitting Co. HENNEPIN CO DEPT HOUSING COMMUNITY	Lab Use- WO # 4040-12-HUS	Phone # 1-612-348-2117
701 4TH AVENUE SOUTH	Acct # 4040	Fax # & E-mail 1-612-348-2920
MINNEAPOLIS, MN 55415		

Project Name: _____ *Special Instructions [include requests for special reporting or data packages]*

Project Location: **4330 LOLAN AVE N.**

Project Number: _____

PO Number: _____ State Of Collection **MN**

Turn Around Time	Matrix / Sample Type (Select ONE)	Tests / Analytes (Select ALL that Apply)		
<input type="checkbox"/> 2 hours* <input type="checkbox"/> Same day* <input type="checkbox"/> 1 business day* <input type="checkbox"/> 2 business day* <input checked="" type="checkbox"/> 3 business days* <input type="checkbox"/> 5 business days* <input type="checkbox"/> Full TCLP (10d) <input type="checkbox"/> Weekend* <small>* not available for all tests</small> <small>Schedule rush organics, multi-metals & weekend tests in advance.</small>	<small>All samples on form should be of SAME matrix type. Use additional forms as needed.</small> <input type="checkbox"/> Air <input type="checkbox"/> Solid <input type="checkbox"/> Aqueous <input type="checkbox"/> Waste <input type="checkbox"/> Bulk <input type="checkbox"/> Wastewater <input type="checkbox"/> Hi-Vol Filter (PM10) <input type="checkbox"/> Water, Drinking <input type="checkbox"/> Hi-Vol Filter (TSP) <input type="checkbox"/> Compliance <input type="checkbox"/> Oil <input checked="" type="checkbox"/> Wipe <input type="checkbox"/> Paint <input type="checkbox"/> Wipe, Composite <input type="checkbox"/> Sludge <input type="checkbox"/> Soil	Asbestos Air / Fiber Counts <input type="checkbox"/> PCM (NIOSH 7400) <input type="checkbox"/> TEM (AHERA) <input type="checkbox"/> TEM (EPA Level II) <input type="checkbox"/> _____ Miscellaneous Tests <input type="checkbox"/> Total Dust (NIOSH 0500) <input type="checkbox"/> Resp. Dust (NIOSH 0800) <input type="checkbox"/> Silica - FTIR (NIOSH 7802) <input type="checkbox"/> Silica - XRD (NIOSH 7500) <input type="checkbox"/> _____	Asbestos Bulk / Asb ID <input type="checkbox"/> PLM (EPA 800/R-93/116) <input type="checkbox"/> PLM (EPA Point-Count) <input type="checkbox"/> PLM (Qualitative only) <input type="checkbox"/> NYELAP 198.1/4/6 <input type="checkbox"/> CAELAP (EPA Interim) <input type="checkbox"/> TEM (Chatfield) <input type="checkbox"/> _____ FOR ASBESTOS AIR: TYPE OF RESPIRATOR USED: _____	Metals-Total Conc. <input checked="" type="checkbox"/> Lead <input type="checkbox"/> RCRA Metals <input type="checkbox"/> _____ <input type="checkbox"/> _____ Metals-Extract <input type="checkbox"/> TCLP / Lead <input type="checkbox"/> TCLP / RCRA Metals <input type="checkbox"/> TCLP / Full (w/ organics) <input type="checkbox"/> _____ Others <input type="checkbox"/> _____

Sample #	Date Sampled	Time Sampled	Sample Identification (e.g. Employee, SSN, Bldg, Material)	Wiped Area (ft²)	Type¹ A,B,P,E	Time²		Flow Rate³		Total⁴ Air Vol
						Start	Stop	Start	Stop	
01	1/27/12	10:30AM	FW, BSMT, V	12" x 12"						
02			FW, ENTLY, CRM	12" x 12"						
03			WW, LIC, V	12" x 3"						
04			FW, SE BR, W	12" x 12"						
05			WS, SE BR, W	12 1/2" x 2 1/2"						
06			FW, PATH, CRM	12" x 12"						
07			FW, UPPR BR, W	12" x 12"						
08			WS, UPPR BR, W	14 1/4" x 2 1/2"						
09			WW, UPPR BR, V	13 1/8" x 3"						
10	✓	✓	FIELD BLANK							

¹Type: A=area B=blank P=personal E=excursion ²Beginning/End of Sample Period ³Pump Calibration In Liters/Minute ⁴Volume in Liters [time in min * flow in L/min]

Sampled by NAME <u>Ben Jones</u> SIGNATURE <u>[Signature]</u> DATE/TIME <u>1/27/12 10:30AM</u>	Relinquished to lab by NAME <u>Ben Jones</u> SIGNATURE <u>[Signature]</u> DATE/TIME <u>1/27/12 6:00PM</u>	<input type="checkbox"/> FX <input type="checkbox"/> UPS <input type="checkbox"/> USM <input type="checkbox"/> HD <input type="checkbox"/> DB WB: _____
---	--	--

Sample return requested Ambient temp Ice °C pH Cl R S X

Chain-of-Custody documentation continues internally within lab. Terms and conditions page 2.

RECEIVED

 8300

SCHNEIDER LABORATORIES GLOBAL

INCORPORATED

2512 W. Cary Street • Richmond, Virginia • 23220-5117
804-353-6778 • 800-785-LABS (5227) • (FAX) 804-359-1475

Over 25 Years of Excellence in Service and Technology

AIHA/ELLAP 100527, ISO/IEC 17025, NVLAP 101150-0, VELAP 460135, NYELAP/NELAC 11413

LABORATORY ANALYSIS REPORT

Lead Analysis based on EPA 7000B Method

Using SLI P26 A14

ACCOUNT #: 4040-12-1566
CLIENT: Hennepin CO Dept Housing Community
ADDRESS: 701 4th Avenue South
Minneapolis, MN 55415

DATE RECEIVED: 1/30/2012
DATE ANALYZED: 1/31/2012
DATE REPORTED: 2/1/2012

PROJECT NAME:
JOB LOCATION: 4330 Logan Ave N.
PROJECT NO.:
PO NO.: HNCTY-50762

Sample Type: SOIL

SLI Sample No.	Client Sample No.	Collection Date	Sample Description	Sample Wt (mg)	Total Lead (μ g)*	Lead Conc (% by wt)	Lead Conc PPM
31335488	01	1/27/2012 11:00 AM	Foundation	563	48.1	0.009	85

Analysis Run ID: 49400

Analyst: Omar H. Elshowaya

Total Number of Pages in Report: 1

Results relate only to samples as received by the laboratory.


Reviewed By **Abisola O. Kasali, Metals Supervisor**
Visit www.slabinc.com for current certifications.

*Minimum Reporting Limit: 10.0 μ g. EPA Soil Std for bare residential soil: 400 ppm by wt in play areas; 1200 ppm by wt in bare soil in the remainder of the yard based on an avg of all other samples collected. EPA does not distinguish between lead-contaminated soil and soil-lead hazards. Soil samples are tested as received unless noted as "Dried before analysis." *Data precision justifies 2 sig. figures. All internal QC parameters were met. Unusual sample conditions, if any, are described.*



SCHNEIDER LABORATORIES GLOBAL, INC.

2512 West Cary Street, Richmond, Virginia 23220-5117
804-353-6778 • 800-785-LABS (5227) • Fax 804-359-1475
www.slabinc.com e-mail: info@slabinc.com

WorkOrderKey



Submitting Co. HENNEPIN CO DEPT HOUSING COMMUNITY	Lab Use- WO # 4040-12-1566	Acct #	Phone # 1-612-348-2117
701 4TH AVENUE SOUTH			
MINNEAPOLIS, MN 55415	4040		1-612-348-2920

Project Name: *Special Instructions [include requests for special reporting or data packages]*

Project Location: **4330 LOGAN AVE N.**

Project Number:

PO Number: State Of Collection **MN**

Turn Around Time	Matrix / Sample Type (Select ONE)	Tests / Analytes (Select ALL that Apply)		
<input type="checkbox"/> 2 hours* <input type="checkbox"/> Same day* <input type="checkbox"/> 1 business day* <input type="checkbox"/> 2 business day* <input type="checkbox"/> 3 business days* <input checked="" type="checkbox"/> 5 business days* <input type="checkbox"/> Full TCLP (10d) <input type="checkbox"/> Weekend* <small>* not available for all tests</small> <small>Schedule rush organics, multi-metals & weekend tests in advance.</small>	<small>All samples on form should be of SAME matrix type. Use additional forms as needed.</small> <input type="checkbox"/> Air <input type="checkbox"/> Solid <input type="checkbox"/> Aqueous <input type="checkbox"/> Waste <input type="checkbox"/> Bulk <input type="checkbox"/> Wastewater <input type="checkbox"/> Hi-Vol Filter (PM10) <input type="checkbox"/> Water, Drinking <input type="checkbox"/> Hi-Vol Filter (TSP) <input type="checkbox"/> Compliance <input type="checkbox"/> Oil <input type="checkbox"/> Wipe <input type="checkbox"/> Paint <input type="checkbox"/> Wipe, Composite <input type="checkbox"/> Sludge <input type="checkbox"/> _____ <input checked="" type="checkbox"/> Soil <input type="checkbox"/> _____	Asbestos Air / Fiber Counts <input type="checkbox"/> PCM (NIOSH 7400) <input type="checkbox"/> TEM (AHERA) <input type="checkbox"/> TEM (EPA Level II) <input type="checkbox"/> _____ Miscellaneous Tests <input type="checkbox"/> Total Dust (NIOSH 0500) <input type="checkbox"/> Resp. Dust (NIOSH 0600) <input type="checkbox"/> Silica - FTIR (NIOSH 7602) <input type="checkbox"/> Silica - XRD (NIOSH 7500)	Asbestos Bulk / Asb ID <input type="checkbox"/> PLM (EPA 600/R-93/116) <input type="checkbox"/> PLM (EPA Point Count) <input type="checkbox"/> PLM (Qualitative only) <input type="checkbox"/> NYELAP 198.11/4/6 <input type="checkbox"/> CAELAP (EPA Interim) <input type="checkbox"/> TEM (Chatfield)	Metals-Total Conc. <input checked="" type="checkbox"/> Lead <input type="checkbox"/> RCRA Metals <input type="checkbox"/> _____ <input type="checkbox"/> _____ Metals-Extract <input type="checkbox"/> TCLP / Lead <input type="checkbox"/> TCLP / RCRA Metals <input type="checkbox"/> TCLP / Full (w/ organics) <input type="checkbox"/> _____ Others <input type="checkbox"/> _____

Sample #	Date Sampled	Time Sampled	Sample Identification (e.g. Employee, SSN, Bldg, Material)	Wiped Area (ft ²)	Type ¹ A,B,P,E	Time ²		Flow Rate ³		Total ⁴ Air Vol
						Start	Stop	Start	Stop	
01	1/27/12	11:00	FOUNDATION							

8300

¹Type: A=area B=blank P=personal E=excursion ²Beginning/End of Sample Period ³Pump Calibration in Liters/Minute ⁴Volume in Liters [time in min * flow in L/min]

Sampled by NAME <u>Ben Jones</u> SIGNATURE <u>[Signature]</u> DATE/TIME <u>1/27/12 11:00AM</u>	Relinquished to lab by NAME <u>Ben Jones</u> SIGNATURE <u>[Signature]</u> DATE/TIME <u>1/27/12 6:00PM</u>	<input type="checkbox"/> FX <input type="checkbox"/> UPS <input type="checkbox"/> USM <input type="checkbox"/> HD <input type="checkbox"/> DB WB: _____
---	--	--

Sample return requested Ambient temp Ice °C pH Cl R S X

Chain-of-Custody documentation continued internally within lab. Terms and conditions page 2.



Hennepin County Housing, Community Works and Transit

Appendix D

Lead Hazard Reduction Recommendations

GMHC - Greater Metropolitan Housing Corporation
15 S 5th St Suite 710
Minneapolis MN 55402

Date: 2/10/2012
RE: 4330 Logan AVE N
Risk Assessor: Jones

Lead Hazard Prioritization: All of the lead hazards listed in the attached lead hazard reduction recommendations can result in lead exposure and should be treated. All lead hazards are **required** to be treated if this property is enrolled in the Hennepin County lead grant program. Lead coated windows and the associated lead dust pose the greatest exposure risk to occupants and if present are prioritized by appearing first in the lead hazard reduction recommendations.

The following recommendations are written based on results of the risk assessment conducted on 1/27/2012.

See attached specifications:



Lead Hazard Reduction Recommendations

4330 Logan AVE N - , Minneapolis MN 55412

All Interior Rooms - (01)

Structure: Miscellaneous

Feature: Dust

Comment: Window wells, window sills, and floors.

Lead Dust Option 1 SMOOTH FLOORS AND WINDOW COMPONENTS (Interim Control Measure)

Treat all smooth floors and window components with the following method. First vacuum area with HEPA vacuum. Next wet-wash with a lead specific detergent with single use paper towels followed by clean water rinse. Finally, vacuum again with HEPA vacuum

Lead Dust Option 2 CARPET (Interim Control Measure)

HEPA vacuum with beater bar attachment or professionally steam clean carpet with two passes in perpendicular directions.

All Interior Rooms - (01)

Structure: Windows

Feature: Window

Comment: Cellar windows only.

Window Option 1 WINDOW REPLACEMENT – TOTAL (Abatement Measure)

Remove package and dispose of entire window unit. Install a pre-hung qualified window unit. Replace casing and/or trim to match original. Prime and topcoat.

Window Option 2 WINDOW REPLACEMENT - VINYL WINDOW (Abatement Measure)

Remove, package and dispose of sashes, parting bead and inner stops. Remove the sash weight. Insulate the sash weight pocket with fiberglass. Install a PVC, one-over-one, double hung, double-glazed combination window with at least a 1/2 screen. Caulk all seams with siliconized acrylic caulk. Install inner stops; if original inner stops are reused, edges are to be sanded smooth and nail holes/dents puttied. Prime and top coat stops with high quality latex or alkyd paint. Laminate and back-caulk outer stop.

Window Option 3 WINDOW REPLACEMENT - JAMB LINER PACKAGE (Abatement Measure)

Remove, package and dispose of sashes, parting beads and inner stops. Inner stops may be reused if architecturally necessary for appearance. Remove the sash weight. Insulate the sash weight pocket. Wet scrape jambs and well. HEPA vacuum all visible dust. Coat jambs and well from inner stops to inner edge of storm window. Install a wood double hung, double-glazed, one-over-one window with vinyl jamb liner or oriel window with vinyl jamb liner. If oriel window, top sash may be fixed. Sashes to be primed/sealed and finish coated to match existing paint or varnish. Laminate and back-caulk well and outer stops with .032 aluminum or vinyl coil stock. Install inner stops, prime and top coat with high quality latex or alkyd paint. If original inner stops are reused, edges are to be sanded smooth and nail holes/dents puttied. Install quality sash lock and handle(s) on lower sash.

Window Option 4 STRIP TO BARE WOOD (Abatement Measure)

Scrape to bare substrate interior and exterior of sashes, interior stops, parting stops, outer stops, header, jamb, well and stool. Minor residue may be cleaned with paint remover. Wash surface with a lead specific detergent or equivalent, rinse, prime

Window Option 5 STABILIZE AND PAINT - ENCLOSE WELL (Interim Control Measure)

Wet scrape all interior and exterior window components including sashes, jambs and stops. Re-glaze as required. Laminate well with back-caulked aluminum or vinyl coil stock. HEPA vacuum all visible dust. Spot prime and topcoat interior and exterior co



Lead Hazard Reduction Recommendations

4330 Logan AVE N - , Minneapolis MN 55412

Window Option 6 STABILIZE AND PAINT (Interim Control Measure)

Wet scrape all interior and exterior window components including sashes, jambs and stops. Re-glaze as required. HEPA vacuum all visible dust. Spot prime and topcoat interior and exterior components.

Exterior Dwelling - (02)

Structure: Doors

Feature: Door

Comment: All deteriorating painted wood doors.

Door Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package and dispose of door, jamb and casing. Install pre-hung door. Re-trim opening. Prime and topcoat.

Door Option 2 STRIP TO BARE WOOD (Abatement Measure)

Scrape to bare substrate all sides of the door(s) noted. Minor residue may be cleaned with paint remover. Package and dispose of paint residue. Wash surfaces with a lead specific detergent or equivalent, rinse. Plane door edges and adjust hasp and str

Door Option 3 PLANE AND ADJUST (Interim Control Measure)

Plane door edges and adjust hasp and strike plate to minimize door/jamb friction and contact. Clean, spot prime/seal, and topcoat.

Door Option 4 STABILIZE AND PAINT (Interim Control Measure)

Stabilize paint by wet scraping and HEPA vacuuming. Clean, spot prime, and topcoat.

Exterior Dwelling - (02)

Structure: Doors

Feature: Door Threshold

Comment: All deteriorating painted door thresholds.

Door Threshold Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package and dispose of lead painted door threshold and/or doorsill. Install replacement components.

Door Threshold Option 2 ENCLOSE DOOR THRESHOLD/SILL (Abatement Measure)

Cut Aluminum coil stock to fit over threshold. Back caulk with siliconized acrylic caulk. Apply coil stock and nail or tack in place.

Door Threshold Option 3 STRIP TO BARE WOOD (Abatement Measure)

Scrape to bare substrate component noted. Minor residue may be cleaned with paint remover. Package and dispose of paint residue. Wash surface with a lead specific detergent or equivalent, rinse, prime, and topcoat. Dry scraping/sanding or operation of

Door Threshold Option 4 STABILIZE AND PAINT (Interim Control Measure)

Mist defective paint area with water. Lightly scrape all loose paint. Rinse and HEPA vacuum all visible chips. Allow surface to dry, seal and topcoat.



Lead Hazard Reduction Recommendations

4330 Logan AVE N - , Minneapolis MN 55412

Exterior Dwelling - (02)

Structure: Exterior Building Components Feature: Exterior Trim

Comment: Window trim and cellar window trim, door trim and jambs, soffit, and fascia.

Exterior Trim Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package and dispose of molding, trim or specified component. Replace components, and caulk with siliconized acrylic. Prep, prime and topcoat.

Exterior Trim Option 2 ENCLOSE (Abatement Measure)

Stabilize surface by wet scraping and HEPA vacuuming. Enclose trim with aluminum coil stock. Back caulk all seams with siliconized acrylic caulk to create an airtight installation.

Exterior Trim Option 3 STABILIZE AND PAINT (Interim Control Measure)

Mist defective paint area with water. Lightly scrape all loose paint. Allow surface to dry; spot prime and topcoat.

Exterior Dwelling - (02)

Structure: Exterior Building Components Feature: Exterior Wall/Siding

Comment: All deteriorating wood walls including the upper wall/gable.

Exterior Wall Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package, and dispose of siding. Weatherize exterior walls.

Exterior Wall Option 2 ENCLOSE (Abatement Measure)

Stencil "Lead Paint" at four-foot intervals on existing surface. Apply a Tyvek or equivalent vapor barrier to enclose the lead containing paint. Protect Tyvek with vinyl or aluminum siding installed in accordance with manufacturer' specifications.

Exterior Wall Option 3 STABILIZE AND PAINT (Interim Control Measure)

Mist defective paint with water to the point of saturation. Lightly scrape all loose paint. Rinse and allow to dry. Spot prime and topcoat.

Garage - (03)

Structure: Exterior Building Components Feature: Exterior Trim

Comment: All painted window components and overhead door casing.

Exterior Trim Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package and dispose of molding, trim or specified component. Replace components, and caulk with siliconized acrylic. Prep, prime and topcoat.

Exterior Trim Option 2 ENCLOSE (Abatement Measure)

Stabilize surface by wet scraping and HEPA vacuuming. Enclose trim with aluminum coil stock. Back caulk all seams with siliconized acrylic caulk to create an airtight installation.

Exterior Trim Option 3 STABILIZE AND PAINT (Interim Control Measure)

Mist defective paint area with water. Lightly scrape all loose paint. Allow surface to dry; spot prime and topcoat.



Lead Hazard Reduction Recommendations

4330 Logan AVE N - , Minneapolis MN 55412

Garage - (03)

Structure: Exterior Building Components **Feature: Exterior Wall/Siding**

Comment: Walls.

Exterior Wall Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package, and dispose of siding. Weatherize exterior walls.

Exterior Wall Option 2 ENCLOSE (Abatement Measure)

Stencil "Lead Paint" at four-foot intervals on existing surface. Apply a Tyvek or equivalent vapor barrier to enclose the lead containing paint. Protect Tyvek with vinyl or aluminum siding installed in accordance with manufacturer's specifications.

Exterior Wall Option 3 STABILIZE AND PAINT (Interim Control Measure)

Mist defective paint with water to the point of saturation. Lightly scrape all loose paint. Rinse and allow to dry. Spot prime and topcoat.

Basement - (04)

Structure: Doors

Feature: Door

Comment: Doors.

Door Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package and dispose of door, jamb and casing. Install pre-hung door. Re-trim opening. Prime and topcoat.

Door Option 2 STRIP TO BARE WOOD (Abatement Measure)

Scrape to bare substrate all sides of the door(s) noted. Minor residue may be cleaned with paint remover. Package and dispose of paint residue. Wash surfaces with a lead specific detergent or equivalent, rinse. Plane door edges and adjust hasp and strike

Door Option 3 PLANE AND ADJUST (Interim Control Measure)

Plane door edges and adjust hasp and strike plate to minimize door/jamb friction and contact. Clean, spot prime/seal, and topcoat.

Door Option 4 STABILIZE AND PAINT (Interim Control Measure)

Stabilize paint by wet scraping and HEPA vacuuming. Clean, spot prime, and topcoat.

Basement - (04)

Structure: Interior Trim

Feature: Trim

Comment: Cellar window trim and door trim.

Interior Trim Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package and dispose of lead painted trim. Repair wall areas damaged in removal process. Install replacement components. Prime and topcoat.

Interior Trim Option 2 ENCLOSE (Abatement Measure)

Stabilize surface by wet scraping and HEPA vacuuming. Enclose trim with a durable material. Caulk all seams and joints with caulk to create an airtight installation.



Lead Hazard Reduction Recommendations

4330 Logan AVE N - , Minneapolis MN 55412

Interior Trim Option 3 STRIP TO BARE WOOD (Abatement Measure)

Scrape to bare substrate of trim members noted. Minor residue may be cleaned with paint remover. Package and dispose of paint residue. Wash surface with a lead specific detergent or equivalent, rinse, prime, and topcoat. Dry scraping/sanding or operat

Interior Trim Option 4 ENCAPSULATE - (Non-Friction Surfaces Only) (Abatement Measure)

Remove package and dispose of all failing substrate. Stabilize all deteriorated paint on sound substrate. Apply 20-year lead-based paint specific encapsulate according to manufacturer's specifications.

Interior Trim Option 5 STABILIZE AND PAINT OR VARNISH (Interim Control Measure)

Mist defective paint area with water. Lightly scrape all loose paint. Rinse and HEPA vacuum all visible chips. Allow surface to dry, seal and topcoat.

SE Bedroom - (10)

Structure: Interior Trim

Feature: Trim

Comment: Window trim.

Interior Trim Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package and dispose of lead painted trim. Repair wall areas damaged in removal process. Install replacement components. Prime and topcoat.

Interior Trim Option 2 ENCLOSE (Abatement Measure)

Stabilize surface by wet scraping and HEPA vacuuming. Enclose trim with a durable material. Caulk all seams and joints with caulk to create an airtight installation.

Interior Trim Option 3 STRIP TO BARE WOOD (Abatement Measure)

Scrape to bare substrate of trim members noted. Minor residue may be cleaned with paint remover. Package and dispose of paint residue. Wash surface with a lead specific detergent or equivalent, rinse, prime, and topcoat. Dry scraping/sanding or operat

Interior Trim Option 4 ENCAPSULATE - (Non-Friction Surfaces Only) (Abatement Measure)

Remove package and dispose of all failing substrate. Stabilize all deteriorated paint on sound substrate. Apply 20-year lead-based paint specific encapsulate according to manufacturer's specifications.

Interior Trim Option 5 STABILIZE AND PAINT OR VARNISH (Interim Control Measure)

Mist defective paint area with water. Lightly scrape all loose paint. Rinse and HEPA vacuum all visible chips. Allow surface to dry, seal and topcoat.

Upper Bedroom - (13)

Structure: Interior Trim

Feature: Trim

Comment: Window trim.

Interior Trim Option 1 REMOVE AND DISPOSE (Abatement Measure)

Remove, package and dispose of lead painted trim. Repair wall areas damaged in removal process. Install replacement components. Prime and topcoat.



Lead Hazard Reduction Recommendations

4330 Logan AVE N - , Minneapolis MN 55412

Interior Trim Option 2 ENCLOSE (Abatement Measure)

Stabilize surface by wet scraping and HEPA vacuuming. Enclose trim with a durable material. Caulk all seams and joints with caulk to create an airtight installation.

Interior Trim Option 3 STRIP TO BARE WOOD (Abatement Measure)

Scrape to bare substrate of trim members noted. Minor residue may be cleaned with paint remover. Package and dispose of paint residue. Wash surface with a lead specific detergent or equivalent, rinse, prime, and topcoat. Dry scraping/sanding or operat

Interior Trim Option 4 ENCAPSULATE - (Non-Friction Surfaces Only) (Abatement Measure)

Remove package and dispose of all failing substrate. Stabilize all deteriorated paint on sound substrate. Apply 20-year lead-based paint specific encapsulate according to manufacturer's specifications.

Interior Trim Option 5 STABILIZE AND PAINT OR VARNISH (Interim Control Measure)

Mist defective paint area with water. Lightly scrape all loose paint. Rinse and HEPA vacuum all visible chips. Allow surface to dry, seal and topcoat.



**Appendix E:
Monitoring Schedule**

The preceding lead reduction recommendations include different ways to treat each lead hazard that was identified by the risk assessment. They are listed in order from most effective to least effective. The most effective treatments are considered abatement and require little or no on-going maintenance to preserve a lead safe environment. The less effective treatments are called interim controls and these treatments require an increased amount of on-going maintenance to preserve a lead safe environment.

If no lead dust, soil, or lead-based paint is found, then no monitoring is required.

If no hazards are found, but lead-based paint is found, an owner's visual survey should occur annually. Re-evaluation shall occur if the owner's visual survey reveals lead-based paint surfaces that have deteriorated, or if the survey reveals the failure of encapsulation or enclosure (if applicable). Re-evaluation shall then occur every two years until two consecutive re-evaluations find no hazards.

If lead dust, soil, or lead-based paint hazards are found to be present, choosing all option number ones with removal of all lead-based paint, will result in no monitoring requirements. If abatement options are chosen that include enclosure, then no re-evaluation is required, but the owner should conduct visual surveys every year to ensure the enclosure has not failed. If the interim control options (stabilize and paint) are chosen then an owner's visual survey should be conducted annually and re-evaluation should occur within two years.

If during the initial lead inspection, lead dust levels are found to be more than ten times the standard levels, found in Appendix C, then re-evaluation after interim control measures should occur six months after the hazard reduction.

Lead-based paint found to be intact at the time of assessment is not included in the previous recommendations. These surfaces should be carefully monitored. A list of these surfaces is provided with this Appendix if applicable.

In general, all painted surfaces should be monitored. A negative result does not necessarily indicate that no lead is present in that surface, but rather indicates that any lead present in that surface does not rise above the 1.0 mg/cm² threshold in the area tested. In addition, during routine maintenance, all painted surfaces should be assumed to contain lead-based paint and treated accordingly unless the included XRF paint testing results indicate that surface does not contain lead-based paint.