



Lead Reduction Check List

4330 Logan AVE N, Minneapolis MN 55412

- Hazard1** All Interior Rooms - (01) Miscellaneous - Dust
 Window wells, window sills, and floors.
- Hazard2** All Interior Rooms - (01) Windows - Window
 Cellar windows only.
- Hazard3** Exterior Dwelling - (02) Doors - Door
 All deteriorating painted wood doors.
- Hazard4** Exterior Dwelling - (02) Doors - Door Threshold
 All deteriorating painted door thresholds.
- Hazard5** Exterior Dwelling - (02) Exterior Building Components - Exterior Trim
 Window trim and cellar window trim, door trim and jambs, soffit, and fascia.
- Hazard6** Exterior Dwelling - (02) Exterior Building Components - Exterior Wall/Siding
 All deteriorating wood walls including the upper wall/gable.
- Hazard7** Garage - (03) Exterior Building Components - Exterior Trim
 All painted window components and overhead door casing.
- Hazard8** Garage - (03) Exterior Building Components - Exterior Wall/Siding
 Walls.
- Hazard9** Basement - (04) Doors - Door
 Doors.
- Hazard10** Basement - (04) Interior Trim - Trim
 Cellar window trim and door trim.
- Hazard11** SE Bedroom - (10) Interior Trim - Trim
 Window trim.
- Hazard12** Upper Bedroom - (13) Interior Trim - Trim
 Window trim.